



Tamura

## LA01P054S05

Nimewo Pati: LA01P054S05

Manifakti / Brand: Tamura

Pwodwi deskripsyon: SENSOR

Datasheets:

[1.LA01P054S05.pdf](#)
[2.LA01P054S05.pdf](#)
RoHS Status:  Plon gratis / RoHS konfòme

Stock kondisyon: 8000 pcs stock

Bato de: Hong Kong

Shipment Way: DHL/Fedex/TNT/UPS/EMS

[DEMANN POU SITASYON](#)

Imaj ka reprezantasyon. Gade espesifikasyon pou detay pwodwi.













### Espesifikasyon nan LA01P054S05

NIMEWO PATI	LA01P054S05
MANIFAKTI	Tamura
DESKRIPSYON	SENSOR
PLON GRATIS STATUS / ROHS STATUS	Plon gratis / RoHS konfòme
KANTITE KI DISPONIB	8000 pcs
DONE FÈY	<a href="#">1.LA01P054S05.pdf</a> <a href="#">2.LA01P054S05.pdf</a>
VOLTAGE - PWOVIZYON POU	4.5 V ~ 5.5 V
SERI	LA01P
KALITE SENSOR	Hall Effect, Open Loop
SANSIBLITE	40mV/A
TAN REPONS	1µs
POLARIZASYON	Bidirectional
ANBALAJ	Bulk
PAKE / KA	Module
SÒTI	Ratiometric, Voltage
LÒT NON YO	9-LA01P054S05ZY MT7412
OPERATING TANPERATI	-40°C ~ 90°C
NIMEWO CHANÈL	1
MOUNTING KALITE	Through Hole
LINEARITE	±1%
PLON GRATIS STATUS / ROHS STATUS	Lead free / RoHS Compliant
FREKANS	DC ~ 400kHz
POU MEZIRE	AC/DC
DETAYE DESKRIPSYON	Current Sensor 54A 1 Channel Hall Effect, Open Loop Bidirectional Module
KOURAN - PWOVIZYON POU (MAX)	10mA
KOURAN - CAPTEUR	54A
PRESIZYON	±1%

### Tags ki gen rapò

Tamura LA01P054S05	LA01P054S05 Distributor	LA01P054S05 Founisè
LA01P054S05 Pri	LA01P054S05 Foto	LA01P054S05 Imaj
LA01P054S05 PDF Datasheet	LA01P054S05 Download Datasheet	LA01P054S05 Datasheet
LA01P054S05 Stock	Achte LA01P054S05	Achte Tamura LA01P054S05
Tamura LA01P054S05	Tamura Founisè	Tamura Distribitè
Tamura LA01P054S05		

### Pwodwi ki gen rapò

 <p><b>LA02P035S03</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 8292 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>LA01M041S05</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 7112 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>LA02P054S03</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 6509 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>LA02P021S03</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 8433 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>LA01M032S05</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 7127 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>LA01P170S05</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 4602 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>LA01P085S05</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 7438 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>LA02P085S03</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 6260 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>LA01M035S05</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 8381 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>LA01M021S05</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 8400 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>LA01P046S05</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 6605 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>LA01P035S05</b> Konpayi fabrikasyon: Tamura Deskripsyon: SENSOR Nan stok: 7069 pcs</p> <p><a href="#">RFQ</a></p>